

## PHOTOGRAPHIC OBSERVATIONS & SOME PROPOSED SOLUTIONS



existing church identification and notices on Quadra Street




Poor state of signage on exterior of church.



Proposed revision of entrance from Quadra - linking to a more inviting entrance to church.




Existing freight delivery hatch to basement.




Mason Street light-well - entry to basement.




Proposed improvements to interior doorways.



Evidence of the slope of the floor of the nave.



Proposed relocation of the Reredos to form a screen that would provide additional, useable space behind.



Observation of the restricted space of the corridor from the Church to the Parish House.

